

Date Revised:	April 2019	Overall Task Risk Rating:	Α			
Description:	Activities that require and/or are related to the manual removal of snow on sidewalks, pathw are not accessible by equipment.	ays, entrances other areas t	hat			
Location(s):	Office, Shop, Asphalt Plant, Snow Projects					
Associated Documents: Housekeeping WTS, Hazardous Agents WTS, Traffic Control WTS, Loading and Unloading WTS, Fueling and						


Associated Documents: Housekeeping WTS, Hazardous Agents WTS, Traffic Control WTS, Loading and Unloading WTS, Fueling and Refueling WTS, Equipment & Machinery Operation WTS, Equipment Repairs (Blocking) WTS, Snow Maintenance Operations WTS

RED FLAGS (HOLD WORK UNTIL CORRECTED):

Note:

If the Worker is under any influence that could affect their ability (drugs, alcohol, fatigue). The worker is not fit for duty.

Not prepared for working in cold



SAFE WORK PRACTICES (SWP)

General Tools and Equipment Practices:

- If you are not familiar with the safe use of any tools or equipment, ask your Foreman / Superintendent for assistance
- Refer to the owner's manual for safety and maintenance information specific to the tool or equipment
- Ensure powered tools or equipment is shut off before commencing fueling / refuelling
- Use tools designed to allow wrist to stay straight avoid using hand tools with your wrist bent
- Use the tools or equipment for it's intended use

Inspections:

- Inspect all tools and equipment before use and record pre-use inspections where required for specific pieces of equipment
- Before starting a tool or equipment, ensure guards and safety devices are in place, adjusted and functioning properly
- All exposed moving or rotating parts must be adequately guarded
- Do not make any protective devices or guarding ineffective

• Do not use defective tool or equipment, remove it from use and inform your foreman / superintendent - they will arrange for it to be serviced Winter Clothing

 Work activity and temperature may vary throughout the day. Dressing in layers allows the worker to add or remove layers as needed. Adjustments to layers should be made prior to work rate or exposure changing to prevent sweating and cooling effects. Generally, three types of layers can be used to increase effectiveness of winter work wear. These are:

Layer	Purpose	Examples
Inner	Absorb moisture and keep it away from the skin.	 Thermal underwear (top and pants) Wool or thermal socks Glove liners
Insulating	Helps keep a layer of warm air trapped around the body.	 Fleece mid-layer (top and pants) Boot liners
Outer	Keeps dust, dirt, wind, and moisture away from the previous layer. Easily removed to prevent the buildup of body heat.	 Balaclava / face mask Arctic-type parka Outer wind-block pants Insulated gloves or mittens Insulated work boots



- Winter Clothing can be bulky and limit mobility. Over protection may result in unnecessary hazards to workers. Winter clothing must protect against the cold and the hazards of the job task but still allow enough mobility and dexterity to complete the task.
- Base layers paired with outer layers are the best method to protect the skin from cold and moisture. Base layers include inner and insulating layers. The purpose of these layers is to draw moisture away from the body and provide the insulation required for the cold exposure of the work environment.
- Outerwear may provide some insulation but its main purpose is to provide protection from wind, moisture and non-winter hazards that are present due to the job task or work environment
- During cold conditions any skin that is uncovered is susceptible to heat loss and cold exposure. Heat loss will occur from your head proportionate to the percentage of body surface area your head, face and neck comprise. Also frostbite of the nose, ears and cheeks are very common. To prevent frostbite and heat loss, the head, face and neck can be protected using balaclavas, hard hat liners, neck warmers and toques.
- Gloves must be made of material that is suitable for the highest severity job hazard and cold exposure while allowing for enough dexterity to perform the task. Two options may be used to protect against job hazards and the cold: insulated gloves or non-insulated gloves paired with liners. Layering increases warmth of fingers and improves dexterity.
- Winter footwear must provide enough insulation to prevent cold exposure injuries, enough traction for the surface they will be used on and protect against other hazards that may be present due the work task or environment.

Cold Stress:

- Frostbite and hypothermia are caused by exposure to severe cold or by contact with extremely cold objects (i.e. metallic objects)
- Once damaged, tissues will always be more susceptible to future frostbite
- Controls include wearing several layers of warm clothing with a waterproof and wind-resistant outer layer and use the Buddy System
- Frostbite Signs and Symptoms are sharp, prickling sensation, skin looks waxy and feels numb
- Hypothermia Signs and Symptoms are shivering, blue lips and fingers, lack of coordination, drowsiness
- If you think someone has signs of cold related illnesses, inform the foreman / superintendent, move the person to a warm area, remove wet clothing, warm affected area gradually, seek medical attention in severe cases

Training:

- Employee Orientations (including roles, responsibilities, applicable workplace task standards, WHMIS, etc.)
- Workers exposed to, or required to work with WHMIS controlled products/material, must be trained in WHMIS accordingly
- Only trained, authorized personnel are allowed to operate or perform maintenance (or do repairs) on tools or equipment
- Only operate tools and equipment that you are authorized and trained to use
- Every worker who may be required to use fire extinguishing equipment shall be trained in its use

Personal Protective Equipment:

- Workers on construction projects must wear, at a minimum, head, foot, eye and high visibility protection
- Full face protection is required when completing tasks that may cause debris / objects to dislodge or become airborne
- Workers must adhere to all requirements of legislated regulations when handling specific designated substances
- Workers must wear all PPE listed in specific materials MSDS / SDS

Environment Canada Wind Chill Chart

.

			Actu	al Air	Temp	eratu	re T _{air}	(°C)				
Wind Speed V _{10 m} (km/h)	5	0	-5	-10	-15	-20	-25	-30	-35	-40	-45	-50
5	4	-2	-7	-13	-19	-24	-30	-36	-41	-47	-53	-58
10	3	-3	-9	-15	-21	-27	-33	-39	-45	-51	-57	-63
15	2	-4	-11	-17	-23	-29	-35	-41	-48	-54	-60	-66
20	1	-5	-12	-18	-24	-30	-37	-43	-49	-56	-62	-68
25	1	-6	-12	-19	-25	-32	-38	-44	-51	-57	-64	-70
30	0	-6	-13	-20	-26	-33	-39	-46	-52	-59	-65	-72
35	0	-7	-14	-20	-27	-33	-40	-47	-53	-60	-66	-73
40	-1	-7	-14	-21	-27	-34	-41	-48	-54	-61	-68	-74
45	-1	-8	-15	-21	-28	-35	-42	-48	-55	-62	-69	-75
50	-1	-8	-15	-22	-29	-35	-42	-49	-56	-63	-69	-76
55	-2	-8	-15	-22	-29	-36	-43	-50	-57	-63	-70	-77
60	-2	-9	-16	-23	-30	-36	-43	-50	-57	-64	-71	-78
65	-2	-9	-16	-23	-30	-37	-44	-51	-58	-65	-72	-79
70	-2	-9	-16	-23	-30	-37	-44	-51	-58	-65	-72	-80
75	-3	-10	-17	-24	-31	-38	-45	-52	-59	-66	-73	-80
80	-3	-10	-17	-24	-31	-38	-45	-52	-60	-67	-74	-81

where T_{ak} – Actual Air Temperature in °C V_{16 m} = Wind Speed at 10 metres in km/h (as reported in weather observations)

1. For a given combination of temperature and wind speed, the wind chill index corresponds roughly to the temperature that one would feel in a very light wind. For example, a temperature of -25°C and a wind speed of 20 km/h give a wind chill index of -37. This means that, with a wind of 20 km/h and a temperature of -25°C, one would feel as if it were -37°C in a very light wind.

Wind chill does not affect objects and does not lower the actual temperature. It only describe how a hum being would feel in the wind at the ambient temperature.

3. The wind chill index does not take into account the effect of sunshine. Bright sunshine may reduce the effect of wind chill (make it feel warmer) by 6 to 10 units.

Frostbite Guide
Low risk of frostbite for most people
Increasing risk of frostbite for most people within 30 minutes of exposure
High risk for most people in 5 to 10 minutes of exposure
High risk for most people in 2 to 5 minutes of exposure
High risk for most people in 2 minutes of exposure or less



Manual Snow Removal Operations

JOB HAZARD AND RISK ANALYSIS	RISK RATING SYSTEM C Low risk of injury or equipment / prop Medium risk of injury or equipment / prop	property damage.
TASK HAZARDS	TASK CONTROLS	RATING
Lack of proper PPE	 Workers must wear the required PPE set out in its SDS Ensure all workers are trained in the PPE that they require 	В
 Forceful exertions – lifting, pushing of snow 	 Use mechanical equipment to remove snow from entrances, sidewalks and paths when and were possible Use a light weight shovel, appropriate to the task, ensuring handle is long enough so as not to stoop 	с
Struck by Equipment / Vehicles	 Ensure all workers are wearing required PPE Workers working near traffic areas must remain vigilant and aware of traffic conditions and the movement of vehicles 	А
 Awkward Postures – Twisting & reaching 	 Use tools only for their intended purposes Push snow with appropriate shovel rather the lifting If need to throw snow, take smaller amounts for easy lift and turn feet to the direction of throw – do not twist at the waist 	с
Repetitive Vibrations & Musculoskeletal Injuries	 When possible, use low vibration tools and equipment Maintain tools and equipment properly Minimize exposure time and frequency of vibrations 	В
Cold Stress	Wearing several layers of warm clothing with a waterproof and wind-resistant outer layer including gloves to reduce skin chaffing and hat or balaclava	
	 Use the Buddy System – watch for signs of cold related illnesses in your co-workers If you think someone has a cold related illness, inform the foreman / superintendent, move the person to a warm area, 	A
	remove wet clothing, warm affected area gradually, seek medical attention in severe cases	
Slips and trips due to icy conditions	Appropriate non-slip footwearApply de-icing materials as necessary	С
Dehydration	Drink water as necessary to maintain hydration	С

SAFE JOB PROCEDURES (SJP)

Pre-Task Commencement:

- 1. Gather, inspect and wear the required PPE for the task (additional high-visibility PPE must be worn when working in low visibility conditions). Replace any damaged or defective PPE as required
- 2. Ensure controls are in place prior to commencing work so risks are mitigated / eliminated
- 3. Determine what equipment / machinery / tools and material, are required for the completion of the task
- 4. Faulty tools or equipment must not be used
- 5. Locate and ensure you are familiar with the operation of the snow removal tools and equipment.
- 6. Do not modify any tool or equipment in any way.
- 7. Do not use tool or equipment if it is damaged. Immediately report any damages to your supervisor.
- 8. Ensure that you have access to water before, during and after the snow shoveling.
- 9. Dress in layers where possible and be aware of the wind chill!
- 10. Stretch your muscles focusing on your upper body.



1.

2.

3.

4.

5.

6.

7.

8.

9.

•

•


•

•

•

•

•



11. Select the proper shovel for your size. Ideally the shovel should come up to your chest. A shovel with a curved handle is best. Remember

- Lifts with your legs...do not bend at your waist. •
- Scoop small amounts of snow into the shovel and walk to where you want to dump it. .
- Do not hold a shovelful of snow with your arms outstretched - it puts too much weight on your spine.

Shoveling stairs:

- Avoid twisting to access the snow or throwing it to the side or over the shoulder ٠
- Stand lower than the step that you are shoveling and pull the snow towards you. Repeat this until you reach the bottom step
- Scoop and lift the snow or push the snow to the disposal area.

Task Completion:

- 1. Ensure all workers are accounted for
- 2. Ensure all equipment / machinery / tools are maintained and stored appropriately in the designated locations
- 3. Implement any housekeeping or maintenance as required